

BRIDGE INSPECTION REPORT

Page 1 of 3

Status: Released

Printed On: 6/2/2021

Agency: Washington State

CD Guid: 1a370985-c5ed-4df5-aa76-cd61dd8db251

Release Date: 5/5/2021

Program Mgr: Evan M Grimm

Br. No. 167/121E

SID 0008114A

Br. Name GREEN RIVER

Carrying SR 167

Route On 00167

Mile Post 19.04

Intersecting GREEN RIVER

Route Under

Mile Post

SIGNATURE ON FILE

Inspector's Signature FPP

Cert # G0710

Cert Exp Date 5/11/2022

Co-Inspector's Signature RAB

Inspections Performed

| Report Type | Inspection Type | Date | Freq | Hours | Inspector | Cert No | Co-Insp. |
|-------------|-----------------|-----------|------|-------|-----------|---------|----------|
| Routine | | 4/10/2021 | 24 | 1.0 | FPP | G0710 | RAB |

| | | | | | | | | | | | |
|---|--------------------------|------------------------|----|--------------------------|------------------------|------|--------------------------|-----------------------|------|--------------------------|----------------------|
| 8 | <input type="checkbox"/> | Alignment (1661) | 52 | <input type="checkbox"/> | Operating Tons (1552) | 1 | <input type="checkbox"/> | Bridge Rails (1684) | 0 | <input type="checkbox"/> | No Utilities (2675) |
| 7 | <input type="checkbox"/> | Deck Overall (1663) | | <input type="checkbox"/> | Op RF (1553) | 1 | <input type="checkbox"/> | Transition (1685) | 0.00 | <input type="checkbox"/> | Asphalt Depth (2610) |
| 6 | <input type="checkbox"/> | Superstructure (1671) | 31 | <input type="checkbox"/> | Inventory Tons (1555) | 1 | <input type="checkbox"/> | Guardrails (1686) | 1967 | <input type="checkbox"/> | Year Built (1332) |
| 7 | <input type="checkbox"/> | Substructure (1676) | | <input type="checkbox"/> | Inv RF (1556) | 0 | <input type="checkbox"/> | Terminals (1687) | 1998 | <input type="checkbox"/> | Year Rebuilt (1336) |
| 9 | <input type="checkbox"/> | Culvert (1678) | 5 | <input type="checkbox"/> | Operating Level (1660) | 32.0 | <input type="checkbox"/> | Bridge Rail Ht (2612) | | | |
| 7 | <input type="checkbox"/> | Chan/Protection (1677) | A | <input type="checkbox"/> | Open/Closed (1293) | | <input type="checkbox"/> | Design Curb Ht (2611) | | | |
| N | <input type="checkbox"/> | Pier/Abut/Prot (1679) | 6 | <input type="checkbox"/> | Structural Eval (1657) | | | | | | |
| 8 | <input type="checkbox"/> | Waterway (1662) | 6 | <input type="checkbox"/> | Deck Geometry (1658) | | | | | | |
| 5 | <input type="checkbox"/> | Scour (1680) | 9 | <input type="checkbox"/> | Underclearance (1659) | | | | | | |

| |
|------------------------------|
| NBIS Risk Category |
| Routine: Low Risk |
| Underwater: No Risk Category |

Inspection Flags

| | | | | |
|---|---|---|--|---|
| <input type="checkbox"/> Soundings (2693) | <input type="checkbox"/> Measure Clearance (2694) | <input type="checkbox"/> Revise Rating (2688) | <input type="checkbox"/> Photos (2691) | <input type="checkbox"/> QA Flag (2695) |
|---|---|---|--|---|

BMS Elements

| Element | Element Description | Total | Units | CS 1 | CS 2 | CS 3 | CS 4 |
|---------|-----------------------------------|-------|-------|-------|------|------|------|
| 12 | Concrete Deck | 9399 | SF | 9395 | 4 | 0 | 0 |
| 26 | Concrete Deck w/Coated Bars | 3856 | SF | 3856 | 0 | 0 | 0 |
| 35 | Concrete Deck Soffit | 13255 | SF | 13252 | 2 | 1 | 0 |
| 105 | Concrete Box Girder | 134 | LF | 126 | 4 | 4 | 0 |
| 115 | Prestressed Concrete Girder | 832 | LF | 827 | 0 | 5 | 0 |
| 200 | Abutment Fill | 2 | EA | 2 | 0 | 0 | 0 |
| 205 | Concrete Pile/Column | 16 | EA | 16 | 0 | 0 | 0 |
| 215 | Concrete Abutment | 116 | LF | 116 | 0 | 0 | 0 |
| 227 | Concrete Submerged Pile/Column | 4 | EA | 4 | 0 | 0 | 0 |
| 310 | Elastomeric Bearing | 16 | EA | 16 | 0 | 0 | 0 |
| 331 | Concrete Bridge Railing | 482 | LF | 482 | 0 | 0 | 0 |
| 361 | Scour | 2 | EA | 1 | 0 | 1 | 0 |
| 370 | Seismic - Longitudinal Restrainer | 10 | EA | 10 | 0 | 0 | 0 |
| 400 | Asphalt Butt Joint Seal | 110 | LF | 55 | 0 | 55 | 0 |
| 405 | Compression Seal / Polymer Header | 110 | LF | 0 | 110 | 0 | 0 |
| 803 | Modified Concrete Overlay | 13255 | SF | 13251 | 4 | 0 | 0 |

BRIDGE INSPECTION REPORT

Page 2 of 3

Status: Released
CD Guid: 1a370985-c5ed-4df5-aa76-cd61dd8db251

Printed On: 6/2/2021
Release Date: 5/5/2021

Agency: Washington State
Program Mgr: Evan M Grimm

| | | |
|---------------------------------|---------------------|-----------------------------|
| Br. No. 167/121E | SID 0008114A | Br. Name GREEN RIVER |
| Carrying SR 167 | | Route On 00167 |
| Intersecting GREEN RIVER | | Mile Post 19.04 |
| | | Route Under |
| | | Mile Post |

| Notes | |
|-------|--|
| 0 | Bridge is oriented south to north and carries NB traffic. Span 2A is the south box girder cantilever span. Span 2B is the prestressed girder drop-in span. Span 2C is the north box girder cantilever span. |
| 12 | Deck is covered with a concrete overlay. See element 803. |
| 26 | Concrete deck with epoxy coated rebar includes the portion of the deck within 16 ft. of the west rail. Deck is covered with a concrete overlay. See element 803. |
| 35 | Soffit has transverse leaching cracks with vertical leaching cracks in the edges. Spans 2A and 2C soffit inside of the restrainer hatches have plywood formwork left in place at a few locations. Span 2A has a 6" x 6" x 1/2" deep spall in the east overhang. Span 2B has an 18" x 8" patch in the east overhang. |
| 105 | Webs have diagonal hairline cracks over the intermediate piers. Bottom of boxes have scattered small shallow spalls and exposed rebar due to lack of cover, up to 8" in length. Span 2 girder seats and stops at the south and north in-span hinges are integral with box girder spans. Girder stops have corner spalls and debris buildup around them. See photo #8. Span 2C bottom of box has diagonal rusty cracks. Span 2C near the hatches has approximately 3 sq. ft. of patching. Span 3 bottom of box has impact damage that has been patched and has scrapes over the bike path at the NE side below the vertical clearance sign. |
| 115 | Girder bottom flanges have scattered area of exposed rebar due to lack of cover and some small patches up to 6" in diameter. The ends have delaminations/spalls in some locations at in-span hinges, up to 12" in length. Girder 2C has a corner spall in the bottom flange at the south end and 20" of exposed rebar in the bottom flange near midspan. Girder 2E has a corner spall in the bottom flange at the north end with exposed strands/rebar. Girder 2G has a corner spall in the bottom flange at the north end with exposed strands/rebar and a 3" x 1-1/2" x 1" deep spall in the web. Girder 2H has a corner spall in the bottom flange at the north end with exposed strands/rebar. See photo #10. REPAIR #14250. |
| 205 | Pier 2 columns have construction scrapes and spalls. |
| 227 | Column 3A has 4 ft. of exposed shaft casing. See photo #6. |
| 310 | Several bearings have shifted off the grout pads at the corners. South in-span bearings 2E, 2G, 2H overhang grout pads up to 1". See photo #4. North in-span bearing 2C overhangs grout pad up to 3/4". |
| 331 | Bridge rails have vertical leaching cracks. |
| 361 | Green River flows east to west under Span 2. South bank has some sloughing under the bridge. See photo #13. North bank has light scattered riprap under the bridge. |
| 370 | There are five longitudinal restrainers at each in-span hinge. Span 2C west and center hatches had the locks cut off with bolt cutters during the 2017 inspection due to corrosion preventing them from opening in order to inspect the seismic restrainers. |
| 400 | South joint is saw cut and is sealed. The north joint is not saw cut and sealed. South joint patches that are breaking up and a 1 ft. x 8" x 3" deep pothole in the right lane have been repaired. North abutment joint has minor edge spalls the largest is 12" x 3". See photo #23. |
| 405 | Joints at Span 2 hinges have been rebuilt with polymer headers. South hinge has a few scattered patches and is leaking. North hinge has a small patch in the HOV lane. |
| 803 | Overlay is worn to aggregate in the wheel lines with a few scattered transverse and longitudinal hairline cracks. Spans 2 and 3 have scattered popouts in the deck 2"- 4" in diameter. See photo #22. Span 2 right lane has approximately 4 sq. ft. of scattered patches. |

BRIDGE INSPECTION REPORT

Page 3 of 3

Status: Released
 CD Guid: 1a370985-c5ed-4df5-aa76-cd61dd8db251

Printed On: 6/2/2021
 Release Date: 5/5/2021

Agency: Washington State
 Program Mgr: Evan M Grimm

| | | |
|---------------------------------|-----------------------|-----------------------------|
| Br. No. 167/121E | SID 0008114A | Br. Name GREEN RIVER |
| Carrying SR 167 | Route On 00167 | Mile Post 19.04 |
| Intersecting GREEN RIVER | Route Under | Mile Post |

Notes (Continued)

- 1677 Banks have soft silts with heavy vegetation up and downstream, some undercutting of vegetation in places. See element 361.
- 1680 A major channel migration would be required for the calculated scour depth to occur. Piers 2 and 3 have 2'-6" thick seals and 4'-0" thick pile caps.
- 1687 Terminals are not slotted.

Repairs

| Repair No | Pr | R | Repair Descriptions | BMS | Noted | Maint | Verified |
|-----------|----|---|---|-----|----------|-------|----------|
| 14250 | 2 | B | Scale loose concrete around spalls in bottom flange corner ends of Girders 2C, 2E, 2G and 2H. Clean rusty bars and coat exposed bars with rust inhibiting paint. (4/13/2013 - Repair rewritten. TKK/RAA) | 115 | 4/4/2009 | | |

Inspections Performed and Resources Required

| Report Type | Date | Freq | Hrs | Insp | CertNo | Coinsp | Note | | |
|-------------------------|-----------|------|------|------|--------|-----------|--|----------|---|
| Routine | 4/10/2021 | 24 | 1.0 | FPP | G0710 | RAB | UBIT is required on a 48 month frequency to inspect Span 2 at hinges, bearings, seismic restrainers and to access hatches. | | |
| Resources | Hours | Min | Pref | Max | Freq | Date | Need Date | Override | Notes |
| SNDG | | | | | 72 | 4/30/2017 | 4/30/2023 | | See the Files Tab for further information. |
| UBIT | 1.50 | 62 | 62 | 62 | 48 | 4/10/2021 | 4/10/2025 | | UB62 is required for 58 ft. out-to-out width. |
| Attenuator | 2.00 | ST | ST | ST | | | | | Attenuator was used for protection of the UBIT and during traffic control setup and takedown. |
| Flagging | 2.00 | ST | ST | ST | | | | | Contact NWR at (425) 339-1778 to arrange for traffic control. |
| Keys | | | | | | | | | Key NM-70 needed for restrainer hatches in soffit (BPO keybox sets #95 to #98). |
| Scheduling Restrictions | | TRFC | TRFC | TRFC | | | | | 2021 Inspection work window: Weekends 6:00am - 7:30am |

WASHINGTON STATE DEPARTMENT OF TRANSPORTATION
NBI STRUCTURE INVENTORY AND APPRAISAL REPORT
(ENGLISH UNITS)

CD Date: 4/10/2021 Printed on: 6/2/2021
CD Guid: 1a370985-c5ed-4df5-aa76-cd61dd8db251

| IDENTIFICATION | | | | WSBIS DATA | | | |
|--|--|--------------------------|-------------------|--|--|----------------|------------------|
| (1) STATE NAME - WASHINGTON | | | 530 | BRIDGE NUMBER | | | 167/121E |
| (8) STRUCTURE NUMBER | | | # 0008114A0000000 | BRIDGE NAME | | | GREEN RIVER |
| (5) INVENTORY ROUTE (ON/UNDER) - On | | | 1 3 1 00167 | CUSTODIAN | | | Washington State |
| STATE ROUTE MILEPOST | | | 19.04 | CROSSING DESC | | | GREEN RIVER |
| (2) HIGHWAY AGENCY DISTRICT - NW Region | | | 01 | MAIN LISTING FLAG | | | M |
| (3) COUNTY CODE 33 - King County | | (4) PLACE CODE | 00000 | SUFFICIENCY RATING | | 90.39 | Not SD or FO |
| (6) FEATURES INTERSECTED | | | GREEN RIVER | CLASSIFICATION | | | |
| (7) FACILITY CARRIED | | | SR 167 | (112) NBIS BRIDGE LENGTH | | | Y |
| (9) LOCATION | | | 4.3 N JCT SR 18 | (104) HIGHWAY SYSTEM - On the NHS | | | 1 |
| (12) BASE HIGHWAY NETWORK - Part of network | | | 1 | (26) FUNCTIONAL CLASS - Prin Arterial - Other Fwy or Expwy | | | 12 |
| (13) LRS INV ROUTE AND SUB ROUTE | | | 16700 | (100) DEFENSE HIGHWAY - Not a STRAHNET route | | | 0 |
| (11) LRS MILEPOST | | | 19.04 | (101) PARALLEL STRUCTURE - Right Hand | | | R |
| (16) LATITUDE | | 47 Deg 22 Min 10.80 Sec | | (102) DIRECTION OF TRAFFIC - 1-way traffic | | | 1 |
| (17) LONGITUDE | | 122 Deg 14 Min 39.50 Sec | | (103) TEMPORARY STRUCTURE - Not Applicable | | | |
| (98A) BORDER BR. - Not a border bridge (98B) (99) BORDER BR. SID - Not a border bridge | | | | (105) FEDERAL LANDS HIGHWAY - Not Applicable | | | 0 |
| STRUCTURE TYPE AND MATERIAL | | | | (110) DESIGNATED NATIONAL NETWORK - Part of network | | | 1 |
| (43) STRUCTURE TYPE MAIN: MATERIAL - Prestressed concrete | | | | (20) TOLL - Non-toll structure | | | 3 |
| DESIGN - Stringer/multi-beam | | | 502 | (21) MAINTENANCE - State Highway Agency | | | 01 |
| (44) STRUCTURE TYPE APPR: MATERIAL - Concrete continuous | | | | (22) OWNER - Washington State | | | 1 |
| DESIGN - Box beam/girder - multiple | | | 205 | (37) HISTORICAL SIGNIFICANCE - Not eligible | | | 5 |
| (45) NO. OF SPANS IN MAIN UNIT | | | 1 | CONDITION | | | |
| (46) NO. OF APPROACH SPANS | | | 2 | (58) DECK | | | 7 |
| (107) DECK STRUCTURE TYPE - Conc. CIP | | | 1 | (59) SUPERSTRUCTURE | | | 6 |
| (108) WEARING SURFACE / PROTECTIVE SYSTEM: | | | | (60) SUBSTRUCTURE | | | 7 |
| (A) TYPE OF WEARING SURFACE - LMC or similar | | | 3 | (61) CHANNEL AND CHANNEL PROTECTION | | | 7 |
| (B) TYPE OF MEMBRANE - None | | | 0 | (62) CULVERTS | | | N |
| (C) TYPE OF DECK PROTECTION - None | | | 0 | LOAD RATING AND POSTING | | | |
| AGE AND SERVICE | | | | (31) DESIGN LOAD - HS 20+Mod | | | 6 |
| (27) YEAR BUILT | | | 1967 | (63) OPER RATING METHOD - Ld Factor (LFR) tons HS20 | | | 1 |
| (106) YEAR RECONSTRUCTED | | | 1998 | (64) OPERATING RATING | | | 52 T |
| (42) TYPE OF SERVICE ON - Highway | | | 1 | (65) INV RATING METHOD - Ld Factor (LFR) tons HS20 | | | 1 |
| UNDER - Waterway | | | 5 | (66) INVENTORY RATING | | | 31 T |
| (28) LANES: ON STRUCTURE 3 | | UNDER STRUCTURE | 0 | (70) BRIDGE POSTING - Equal or above legal loads | | | 5 |
| (29) AVERAGE DAILY TRAFFIC | | | 69129 | (41) STRUCT OPEN, POSTED, CLOSED - Open, no restrictions | | | A |
| (30) YEAR OF ADT 2019 | | (109) TRUCK ADT | 10% | APPRAISAL | | | |
| (19) BYPASS, DETOUR LENGTH | | | 1 mi | (67) STRUCTURAL EVALUATION | | | 6 |
| GEOMETRIC DATA | | | | (68) DECK GEOMETRY | | | 6 |
| (48) LENGTH OF MAXIMUM SPAN | | | 150 ft | (69) UNDERCLEARANCES, VERTICAL & HORIZONTAL | | | N |
| (49) STRUCTURE LENGTH | | | 241 ft | (71) WATERWAY ADEQUACY | | | 8 |
| (50) CURB OR SIDEWALK: LEFT 0.0 ft | | RIGHT | 0.0 ft | (72) APPROACH ROADWAY ALIGNMENT | | | 8 |
| (51) BRIDGE ROADWAY WIDTH CURB TO CURB | | | 54.0 ft | (36) TRAFFIC SAFETY FEATURES | | | 1110 |
| (52) DECK WIDTH OUT TO OUT | | | 57.2 ft | (113) SCOUR CRITICAL BRIDGE | | | 5 |
| (32) APPROACH ROADWAY WIDTH (W/SHOULDERS) | | | 54 ft | PROPOSED IMPROVEMENTS | | | |
| (33) BRIDGE MEDIAN - No median | | | 0 | (75) TYPE OF WORK - | | | 351 |
| (34) SKEW 8 Deg | | (35) STRUCTURE FLARED | No 0 | (76) LENGTH OF STRUCTURE IMPROVEMENT | | | 241 ft |
| (10) INVENTORY ROUTE MIN VERT CLEAR | | | 99 ft 99 in | (94) BRIDGE IMPROVEMENT COST | | | \$2,699,000 |
| (47) INVENTORY ROUTE TOTAL HORIZ CLEAR | | | 54 ft 00 in | (95) ROADWAY IMPROVEMENT COST | | | \$540,000 |
| (53) MIN VERT CLEAR OVER BRIDGE RDW | | | 99 ft 99 in | (96) TOTAL PROJECT COST | | | \$5,398,000 |
| (54) MIN VERT UNDERCLEAR | | | 0 ft 00 in N | (97) YEAR OF IMPROVEMENT COST ESTIMATE | | | 2014 |
| (55) MIN LAT UNDERCLEAR RT | | | 0.0 ft N | (114) FUTURE ADT | | | 97610 |
| (56) MIN LAT UNDERCLEAR LT | | | 0.0 ft | (115) YEAR OF FUTURE ADT | | | 2039 |
| NAVIGATION DATA | | | | INSPECTIONS | | | |
| (38) NAVIGATION CONTROL - No nav control | | | 0 | (90) INSPECTION DATE 04/21 | | (91) FREQUENCY | 24 MO |
| (111) PIER PROTECTION - Not Applicable | | | | (92) CRITICAL FEATURE INSPECTION: | | (93) CFI DATE | |
| (39) NAVIGATION VERTICAL CLEARANCE | | | 000 ft | (A) FRACTURE CRIT DETAIL - NO - | | Month | (A) __/__/__ |
| (116) VERT-LIFT BRIDGE NAV MIN VERT CLR | | | | (B) UNDERWATER INSP - NO - | | Month | (B) __/__/__ |
| (40) NAVIGATION HORIZONTAL CLR | | | 0000 ft | (C) OTHER SPECIAL INSP - NO - | | Month | (C) __/__/__ |